

From: [Gary Moore](#)
To: webster.susan@epa.gov
Subject: Fw: Delta Shipyards
Date: 07/02/2012 03:00 PM
Attachments: [Photo 1.jpg](#)
[Photo 2.jpg](#)
[Photo 3.jpg](#)
[Photo 4.jpg](#)
[Photo 5.jpg](#)
[Photo 6.jpg](#)
[Photo 7.jpg](#)
[Photo 8.jpg](#)
[Photo 9.jpg](#)
[Photo 10.jpg](#)
[Photo 11.jpg](#)

Take a look at the photos for Delta Shipyards. A lot of vegetation!!!!

Gary Moore
 Federal On-Scene Coordinator
 EPA Region 6
 Cell: 214-789-1627
 Work: 214-665-6609
 email: moore.gary@epa.gov

----- Forwarded by Gary Moore/R6/USEPA/US on 07/02/2012 02:59 PM -----

From: "Wright, Jeff" <Jeff.Wright@WestonSolutions.com>
 To: Gary Moore/R6/USEPA/US@EPA
 Cc: "Bordelon, David" <David.Bordelon@WestonSolutions.com>, "Sherman, Robert" <Robert.Sherman@WestonSolutions.com>
 Date: 06/19/2012 10:37 AM
 Subject: Delta Shipyards

Gary –

Just wanted to touch base with you regarding Delta Shipyards. The Draft QASP has been forwarded to Ceci for review and I'll send it to you as soon as I can. Michelle and Brenda have decided to run full scale analysis (VOCs, SVOCs, Pesticides/PCBs, Herbicides, and TAL Metals) on all their samples. Historical data show the COCs as SVOCs (PAHs) and metals. Their rationale is that due to the age of the data they would like to have full scale analysis to cover all the bases. Just wanted to confirm that we will be running the same analyses with the addition of TCLP VOCs, TCLP SVOCs and TCLP Metals for the Pit Characterization samples. Robert and I conducted the site recon on 6-7-12 and spoke with the daughter of the property owner. Her name is (b) (6) (b) (6). Her father (Property Owner) is Lynn B. Dean. She said that he does suffer from (b) (6). She and her mother (b) (6) have Power of Attorney. I've attached a few Photos for your review, as you will be able to see the site will need clearing before we could get any type of sampling equipment in there.

Below are the descriptions of the Photos:

Photo 1 – Overgrown Vegetation on west side of Pit 3

Photo 2 – View of Drainage ditch area south of Pit 3

Photo 3 – Overgrown vegetation along east side of Pits 1 & 2

Photo 4 – View of Pit 2

Photo 5 – View of Pit 2

Photo 6 – View of Pit 3

Photo 7 – View of Pit 3

Photo 8 – Sheen on water within Pit 3

Photo 9 – Piping in berm between Pits 2 & 3

Photo 10 – View of overgrown vegetation along west berm of Pit 3

Photo 11 – View of overgrown vegetation along west berm of Pit 2



Jeff Wright, CHMM

Weston Solutions, Inc.

an employee-owned company

13702 Coursey Blvd.,

Bldg #7, STE A

Baton Rouge, LA 70817

(225) 297-5415 Direct

(225) 278-8406 Cell

Jeff.Wright@westonsolutions.com

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.



Photo 1.jpg



Photo 2.jpg



Photo 3.jpg



Photo 4.jpg



Photo 5.jpg



Photo 6.jpg



Photo 7.jpg



Photo 8.jpg



Photo 9.jpg



Photo 10.jpg



Photo 11.jpg



06/07/2012 09:21



06/07/2012 09:24



06/07/2012 09:35



06/07/2012 09:49



06/07/2012 09:49



06/07/2012 09:59



06/07/2012 09:59



06/07/2012 10:02



06/07/2012 10:17



06/07/2012 10:24



06/07/2012 10:24